

Connecticut River Aquatic Habitat Connectivity

Fish Passage in the White River Watershed

Nason Brook at the Woodlawn Cemetery, Rochester Vermont



Before



After

Left: A view of the Nason Brook culvert outlet showing the damage from TS Irene. **Right:** Nason Brook Bridge allowing for aquatic organism passage and flood resiliency.

Site description: Nason Brook in Rochester Vermont is a headwater tributary to the White River and supports a thriving fishery including Atlantic salmon and a wild brook trout population. This new bridge allows native brook trout to access 4 miles of critical thermal refugia and spawning habitat.

Problems / history: Multiple culverts in Vermont were in need of emergency repair following the flooding from tropical storm Irene in August of 2011. Following tropical storm Irene many of the emergency fixes were designed to quickly open roads for vehicle traffic, but not always allow for fish and aquatic organism passage. Working closely with FEMA and the town of Rochester the US Fish and Wildlife Service has provided technical assistance, engineering designs, and project over site to ensure projects allow both fish and aquatic organism passage.

Objective and Method: Tropical Storm Irene devastated much of the White River basin. Our objective is to insure that brook trout habitat is available and healthy post flooding. Our goal is to maintain healthy, sustainable brook trout populations. Proactively assisting towns will lead to projects large enough to sustain future catastrophic events while maintaining the exceptional fishery.

Partners and Funding: Funding and support for this project came from the US Forest Service, FEMA, Town of Rochester, White River Partnership, and the US Fish and Wildlife Service.

<u>Cost:</u>	<u>USFWS</u>	<u>FEMA</u>	<u>TOTAL</u>
	\$14,925	\$29,950	\$40,875